ABSTRACT

A method of hard coating a lens includes maintaining a dip tank at a temperature T_D , wherein the dip tank includes a liquid including a primer or a hard coat solution. The lens is dried and heated to a temperature T_L . The lens is dipped into the dip tank wherein T_L is within 20 degrees F of T_D .

5

30

1 2